GOVERNMENT OF ANDHRA PRADESH <u>ABSTRACT</u>

Public Services – R&B Department – Sri P.Ramulu, the then Deputy Executive Engineer (R&B) Zaheerabad, Executive Engineer (R&B), Nizamabad – Certain irregularities committed – Departmental Enquiry conducted – Further action dropped – Orders – Issued.

TRANSPORT, ROADS & BUILDINGS (VIG.I) DEPARTMENT

(120.2)

G.O.Rt.No. 769

Dated: 09.08.2010. Read the following:-

- 1) From the Director-General, Genl.Admn.(V&E) Department, Vig. Report No.95 (142/V&E/E2/04), dated: 30.06.2005.
- 2) G.O.Rt.No.1452, TR&B (Vig.I) Dept. dated: 26.09.2008.
- 3) From Sri Janak Raj, IPS (Retd), COI, D.O.Lr.No.1693/ COI.JR/2008, dt.27.10.2009.
- 4) Govt.Memo.No.9245/Vig.I.2/2005-7, Dated: 08.02.2010.
- 5) From the ENC (R&B), Admn., Lr.No.1914/VC(1)/05, dt.04.05.2010.

An enquiry has been held against Sri P.Ramulu, the then Deputy Executive Engineer (R&B) Zaheerabad, Executive Engineer (R&B), Nizamabad for his failure in ensuring the work of improvements to PWD road to Karnataka Border via Ramatheertha, Samshillapur. The Enquiry Officer submitted his enquiry report.

- 2. The Enquiry Officer's report, under Rule 21(2) of APCS (CC&A) Rules, 1991, has been communicated to the above said Officer to make a representation if any.
- The Charged Officer, in his representation, has submitted that the Vigilance & Enforcement authorities have inspected the work at initial stages and found certain deficiencies. The V&E authorities did not find any deficiencies in the thickness of the crust laid and the deficiencies were found in the lab tests only. The work carried out in cold mix process and spreading done manually uniform mixing and spreading cannot be ensured fully and there would be certain loose packets or deficiencies. The recording of work and check-measuring the same would be based on the quantity of the material consumed on the work but there is no specific checking process contemplated/ envisaged for measuring and check measuring any work. However, payments would be regulated based on the quality control reports and the recommendations thereof. Further since this work is entrusted on L.S. agreement, the maintenance of quality during the execution and also during the period of observation period lies on the Contractor. The deficiencies found by V&E were rectified to the satisfaction of the joint inspection of Quality Control, SE and the SE, Medak. Further submitted the deficiencies that were noticed were rectified by the Contractor, there is no loss for the Government and the work is completed as per the specifications of the agreement. Since, the final payments cannot be made without the periodical inspections of Quality Control and requested to drop further action against him as he due for retirement on 31-8-2010 on attaining the age of Superannuation.
- 4. Government, after careful examination of the matter, have observed that final payment would be made only after Quality Control Inspection and the works were rectified. Hence, it is decided to drop

further action against Sri P.Ramulu, the then Deputy Executive Engineer (R&B) Zaheerabad, Executive Engineer (R&B), Nizamabad.

- 5. Government hereby drop further action against Sri P.Ramulu, the then Deputy Executive Engineer (R&B) Zaheerabad, Executive Engineer (R&B), Nizamabad.
- 6. The Engineer-in-Chief (R&B) Admn., shall take necessary action accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

D.LAKSHMI PARTHASARATHY PRINCIPAL SECRETARY TO GOVERNMENT

Τo

Sri P.Ramulu, the then DEE (R&B) Zaheerabad, now EE (R&B), Nizamabad.

Thro: the Engineer-in-Chief (R&B) Admn., Hyderabad.

The Engineer-in-Chief (R&B) Admn., Hyderabad.

Copy to

The Director General, Vigilance & Enforcement Department, BRKR Bhavan, Hyderabad.

The Secretary to VC, APVC, Hyderabad. Sf/Sc

//FORWARDED :: BY ORDER//

SECTION OFFICER